

Press Release March 13th 2014

Grandstand repaired with HB40 at Fakenham Racecourse

Repairs were required to the underside of the Grandstand at Fakenham Racecourse where steel reinforcement had corroded causing the concrete to spall.

Ronacrete Approved Contractor Apolodor was contracted to carry out the repairs to the concrete structure. Apolodor broke out the damaged concrete fully exposing the steel and removed corrosion before treating the steel with **Ronacrete Standard Primer.** The concrete was repaired by application of **RonaBond HB40**.

RonaBond HB40 is a pre-packed high build polymer modified concrete repair mortar. It is used to repair concrete on vertical surfaces and soffits. It is typically applied in layers up to 50mm thick on walls on walls and 30mm thick on soffits.



A prepared area after removal of spalled concrete and cleaning of the reinforcement



The same area after application of the repair mortar

Ends

Ronacrete Ltd Tel: 01279 638700

Email: tech@ronacrete.co.uk
Web: www.ronacrete.co.uk